



GERARD CHIMNEY COMPANY



60. Breeching interior - elevation 18' above ground level - breeching rusted.



61. Interior surface metal breeching - elevation 18' above ground level - heavy rust.




62. Interior surface metal breaching - elevation 18' above ground level - heavy rust.



63. Interior surface metal breaching - elevation 18' above ground level - heavy rust.

GERARD CHIMNEY COMPANY



64. Interior surface metal breaching - elevation 18' above ground level - heavy rust.




65. Interior surface metal breaching - elevation 18' above ground level - heavy rust.




66. Interior surface metal breaching - elevation 18' above ground level - heavy rust - weld seam cracked.


GERARD CHIMNEY COMPANY



67. Interior surface metal breaching and access door - north side - elevation 18' above ground level - heavy rust.



68. Interior surface, metal breaching and access door - north side - elevation 18' above ground level - heavy rust - weld seam rusted through.




69. Exterior surface metal breaching and access door - north side - elevation 18' above ground level - weld seam rusted through - heavy rust.

GERARD CHIMNEY COMPANY



70. Breaching access door - north side - elevation 18' above ground level - heavy rust - frame rusted through




71. Breaching access door - north side -
elevation 18' above ground level -
heavy rust - frame rusted through


GERARD CHIMNEY COMPANY




72. Exterior surface metal breaching and access door - north side and bottom - elevation 18' above ground level - heavy rust.



73. Exterior surface - full view from base - good condition.




74. Exterior surface - east side - elevation 5' above ground level - good condition.



75. Exterior surface - east side - elevation 10' above ground level - good condition.


GERARD CHIMNEY COMPANY



76. Exterior surface and breeching entry - east side - elevation 15' above ground level - good condition.



77. Exterior surface and watertable - east side - elevation 20' above ground level - good condition.




78. Exterior surface - east side - elevation 20' above ground level - good condition.



79. Exterior surface - east side - elevation 30' above ground level - good condition.


GERARD CHIMNEY COMPANY



80. Exterior surface - east side - elevation 40' above ground level - good condition.



81. Exterior surface and downlead - east side - elevation 50' above ground level - good condition.




82. Exterior surface and downlead - east side - elevation 60' above ground level - good condition.



83. Exterior surface - east side - elevation 70' above ground level - good condition.

GERARD CHIMNEY COMPANY



84. Exterior surface - east side - elevation 80' above ground level - good condition.



85. Exterior surface and downlead - east side - elevation 90' above ground level - good condition.